

LTPP SPS Project Deviation Report Project Summary Sheet		State Code Project Code	<u>28</u> <u>0500</u>
Project Classification Information			
SPS Experiment Number: <u>SPS-5</u>		State or Province: <u>Mississippi</u>	
LTPP Region:		<input type="checkbox"/> North Atlantic <input type="checkbox"/> North Central <input checked="" type="checkbox"/> Southern <input type="checkbox"/> Western	
Climate Zone:		<input type="checkbox"/> Dry-Freeze <input type="checkbox"/> Dry-No Freeze <input type="checkbox"/> Wet-Freeze <input checked="" type="checkbox"/> Wet-No Freeze	
Subgrade Classification:		<input checked="" type="checkbox"/> Fine Grain <input type="checkbox"/> Coarse Grain <input type="checkbox"/> Active (SPS-8 Only)	
Project Experiment Classification Designation (SPS 1, 2 and 8):		<u>N/A</u>	
Construction Start Date: <u>13 August '90</u>		Construction End Date: <u>26 Sept. 1990</u>	
Deviation Summary			
Site Location Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Construction Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Data Collection and Processing Status Summary			
Inventory Data (SPS 5,6,7,9):		<input type="checkbox"/> Complete Submission <input checked="" type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input type="checkbox"/> NA	
Materials Data:		<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete/No Test Data	
Construction Data:		<input checked="" type="checkbox"/> All Required Data Obtained <input type="checkbox"/> Incomplete/Missing Data Elements	
Historical Traffic Data:		<input checked="" type="checkbox"/> All Required Historical Estimates Submitted (SPS 5,6,7,9) <input type="checkbox"/> Required Estimates Not Submitted <input type="checkbox"/> NA	
Traffic Monitoring Equipment:		<input checked="" type="checkbox"/> WIM Installed On-Site <input type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input type="checkbox"/> No Equipment Installed	
Traffic Monitoring:		<input type="checkbox"/> Preferred <input checked="" type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input type="checkbox"/> Site Related	
Traffic Monitoring Data:		<input checked="" type="checkbox"/> Monitoring Data Submitted <input type="checkbox"/> No Monitoring Data Submitted	
FWD Measurements:		<input checked="" type="checkbox"/> Preconstruction Tests Performed <input type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed	
Profile Measurements:		<input checked="" type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed	
Distress Measurements:		<input checked="" type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-construction Tests Performed	
Maint. & Rehab. Data:		<input checked="" type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input type="checkbox"/> NA	
Report Status			
Materials Sampling and Test Plan:		<input checked="" type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA	
Construction Report:		<input checked="" type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA	
AWS: (SPS 1, 2, & 3)		<input type="checkbox"/> AWS Installed <input type="checkbox"/> AWS Installation Report Submitted to FHWA <input type="checkbox"/> NA	

LTPP SPS Project Deviation Report
Site Location Guidelines Deviations

State Code
Project Code

28
0500

- ☐ Comments Pertain to All Test Sections on Project
☐ Comments Pertain Only to Section(s): (Specify) _____

Site Location Guideline Deviation Comments

- In order to meet requirements for cut/fill (avoid transitions), ~~the~~ available space for site layout was limited. In some cases only 25 ft was left for transitions between sections.

Mark P. [Signature]

10/15/96

LTPP SPS Project Deviation Report
Construction Guidelines Deviations

State Code
Project Code

28
0500

- ☐ Comments Pertain to All Test Sections on Project
☐ Comments Pertain Only to Section(s): (Specify) _____

Construction Guidelines Deviation Comments

- One of the first SPS projects constructed in the country - lacking any guidelines for MSFT, Construction, or Data Collection, we did the best we could.
- Numerous problems encountered during HMA placement - mix production very inconsistent due to plant problems. Caused delays in construction trying to get voids right.

M. P. [Signature]

10/15/96

